

## EMS ROMBLON CONDUCTS INSPECTION OF DUMPSITE, EMB-FUNDED MRF IN FERROL

The Environmental Management Services (EMS)-Romblon conducted site inspection of dumpsite and EMB-Funded Materials Recovery Facility (MRF) in the Municipality of Ferrol, Romblon on February 10, 2021.

The inspection and monitoring was headed by Engineer II Wilsone Ray Año, together with Environmental Monitoring Officers (EnMOs) Jose Marie Fabito and Jeiel Lachica.

Said activity was conducted in coordination with Ferrol Municipal Planning and Development Coordinator Noli Muyargas.

The inspection was made to monitor the compliance of the Local Government Unit of Ferrol to the environmental laws, particularly its compliance to the Republic Act 9003 (Ecological Solid Waste Management Act of 2000), that are being enforced by the Environmental Management Bureau.

